

SAMMITR (Australia) Pty Ltd
 10 Greens Road DANDENONG VIC 3175
 Tel: 03 9706 7194
 ABN: 58 153 617 773

SMM Technical Bulletin		
Bulletin Number:	23042018	
Subject:	Tilt and Shock Indicator Labels	
Date:	23rd April 2018	

Dear Dealers,
 Sammitr Australia will be implementing special new labels to our canopy packaging. These new labels will help customers recognize potentially damaged in transit canopies. The Shock Watch and Tilt Indicator Labels will now be attached to the outside of our canopy boxes.

ShockWatch Labels indicate when an item has been exposed to a potentially damaging impact during transit or in storage. ShockWatch labels are tamperproof, mechanically activated devices that **turn bright red when an impact occurs** over the g force threshold of the ShockWatch label. Shockwatch Labels have an omni-directional impact response.

TiltWatch tilt indicator detects unacceptable tilting on goods that must remain upright. When these indicators are used, the product cannot be tipped without indisputable evidence of mishandling. The tilt indicator **turns red if the container it is affixed to is tilted past 80°** or is completely upended.





SAMMITR (Australia) Pty Ltd
10 Greens Road DANDENONG VIC 3175
Tel: 03 9706 7194
ABN: 58 153 617 773

These new labels will be located on the side of the canopy box above and below the product label as shown.

We will use one ShockWatch and Tilt indicator per canopy. Customers will need to still follow our Damaged in Transit Procedure, however in the case if any of these labels are activated they should carefully check the whole canopy and report any issues on POD.

The below links contain some more information on these new labels.

[> ShockWatch Labels Brochure](#)

[> TiltWatch XTR Brochure](#)

Yours Sincerely,

Sammitr Australia Team

